

HANDICAP DETECTABLE WARNING PAVERS

COPPERTONE


MEDIUM IRONSPOT #46

MANGANESE IRONSPOT

ROSE BLEND

DARK IRONSPOT

MEDIUM IRONSPOT #77



Additional Handicap Detectable Warning Pavers

- 1/2" x 3 5/8" x 7 5/8"
- 1 1/4" x 4" x 8"
- 1 5/8" x 3 5/8" x 7 5/8"
- 1 5/8" x 4" x 8"
- 2 1/4" x 3 5/8" x 7 5/8"
- 2 1/4" x 4" x 8"

Endicott Handicap Detectable Warning Pavers are designed and manufactured to incorporate a truncated dome surface which the vision-impaired can identify by touch, yet provides traversable service for the non-impaired and those in wheelchairs. Handicap detectable warning surfaces were mandated by the American Disabilities Act of 1990, and are required in the following areas:

- curb cuts and curb ramps (not on handicap ramps at stairs)
- between a hazardous vehicular area and a pedestrian walkway where the walkway is not separated by bollards, curbs or other elements
- at the edge of a reflecting pool where the pool is not delineated by walls, bollards, curbs or other elements

Endicott Handicap Detectable Warning Pavers are available in a variety of nationally recognized Ironspot colors to meet color contrast requirements.




Consult the American Disabilities Act of 1990 Accessibility Guidelines for exact requirements and usage.

See reverse side for Bonding Pattern Options

Endicott Clay Products Company

Post Office Box 17
Fairbury, Nebraska 68352
402/729-3315
Fax: 402/729-5804



Endicott